
Tacera Suite 4.9 Release Notes

RN-US-023

1 Revision History

Rev	ECO Number	Description
A	18-155	Initial release of version 4.9.0

2 Scope

The following release notes are for the release of Tacera Suite v4.9.

3 Release

3.1 Release 4.9.0

WARNING: This release is incompatible with pre-4.6.0 releases of Tacera Suite. All of the modules **MUST** be deployed together in a single maintenance window. Release 4.6.0 contains a breaking change in the library handling inter-process communication that prevents it from being backward-compatible with older software modules.

3.1.1 General Notes

Tacera Release V4.6 onwards changes the software license implementation and requires a new license to be generated and deployed. Refer to *SIM-026, Tacera Licensing Installation and Configuration Guide* for more details. A floor controller not correctly configured to access the license server (Integration Gateway) will fail to startup.

3.1.2 New Features

Component	Description
Tacera Suite	Added general support for new RTLS reports in the Pulse Suite.

3.1.3 Bug Fixes

Component	Zendesk #	Description
Tacera Site Configuration	N/A	Setting 'Presence' category for newly added call type results in no staff asset logging in database for reporting.
Tacera IP Connect Server	N/A	IP-CPS-4B should be counted as a single device in license enforcement.
	N/A	Integration callpoint used for ODL/ZTS activation now allow uniqueness for a minimum of 150 locations. This fixes an issue where the ODL was not always activated on INTG* call point activation (used in a RTLS integration deployment).
ACS Platform 4	23318	Corrected issues where UDP messages were being using the physical IP address of the ACS in a redundant pair instead of the Virtual IP. This resulted in the time sync messages being rejected on the IP-Duty and resulting in out of sync clocks.

3.1.4 Known Issues

Component	Zendesk #	Description
N/A	N/A	N/A

3.1.5 Released Documents

Document	Revision
CS-005, IP-TalkTwo/VoIP	A
SIM-026, Tacera Licensing Guide	D
SIM-028, Tacera Room Controller Configuration Guide	B
SIM-017, Tacera Hardware Installation and Cabling Guide	C
SIM-010-v4.9, Tacera IP-CONNECT Configuration Guide	A
SIM-035, Tacera TalkTwo/VoIP Installation and Configuration Guide	A
TIS-061, Callpoint Assembly Screws	B

3.1.6 Components

Component	Version	MD5 Hash
ACS-VM Platform 4 OVA	4.0.27	f987f87a61cdfff7d78c7fb6854b6b15
ACS Platform 4 Patch	4.0.40	11d29668a7344263c29c2560662d9da0
ACS-110 Platform 3 Patch	3.5.19	27628fa7c7642c329e30843b147f08d5
Tacera Echostream Config	4.0.1	49355fde6e3ac7caa699571a6ce23f08
Tacera IP Connect Server	4.9.4	09e5c325f40acdd9ee76c77af044c53e
Tacera Map Editor	4.0.2	4dd61d0caed4cce817e56ee8b4d889e5
Tacera Nurse Station (IP-TSNS)	4.9.3	7314c6a165bae3240c447ae8fe0b2745

Tacera Site Configuration	4.9.1	abd4c94557b43c1eade93674b0f8eb2c
Tacera SNMP Agent	4.1.3	1be62318361c4d1fc852aca734bba423
Tacera TAP In	1.0.10	a060f77625c3b3850dde9f5608382431
Tacera Integration Gateway	1.1.3	909f2b91f13529a919c24629fbc17fa9
ARK-1 USB Recovery Tool	2.0.3	c61cc74434152b61f55743c69fdd8893
IP-PST Application	1.7.25	1a59b6222dda84d9a6585ba29f642a6b
IP-CCT Firmware	2.1.28	e2d50d598542da66f0e6f9baa7997e03
IP-ANPD1 Firmware	1.16	5d0f4e3167e7ce0f5b3e4f4cc4245f11

3.1.7 Compatibility Matrix

Component	Platform Compatibility
ACS-VM Platform 4 OVA	Enterprise Server
ACS Platform 4 Patch	ACS Platform 4
ACS-110 Platform 3 Patch	ACS Platform 3
Tacera Echostream Config	Windows PC
Tacera IP Connect Server	ACS Platform 4, ACS Platform 3
Tacera Map Editor	Windows PC
Tacera Nurse Station (IP-TSNS)	IP-TSNS
Tacera Site Configuration	Windows PC
Tacera SNMP Agent	ACS Platform 4, ACS Platform 3
Tacera TAP In	ACS Platform 4, ACS Platform 3
Tacera Integration Gateway	ACS Platform 4
ARK-1 USB Recovery Tool	IP-ARK-1
IP-PST Application	IP-PST, IP-PST-F/BE, IP-PST2
IP-CCT Firmware	IP-CCT
IP-ANPD1 Firmware	IP-ANPD1

For further information contact Austco Support on support@ustco.com.